

CERTIFICATE

**Welding of railway vehicles and components according to:
EN 15085-2**

This Certificate is issued to:

**NAIVAN
Fuentecillas, 17-19; Júndiz
01015 Vitoria (Álava)
Spain**

Is qualified to perform welding work within the range of certification of

Certification Level CL1 according to EN 15085:2007 Part 2

Scope: New manufacture of components for the railway sector.

Welding processes and base material groups:

Procesos de soldeo	Grupo de material base	Detalles
131	22	1.5 – 20 mm
131	23	1.5 – 12 mm
135	1	1-20 mm BW, FW (from 5mm), hasta 355 Mpa
135	2	1.5 – 6.5 mm SC sl BW Up to 700 MPa
135	2	2.1 – 6 mm SC sl FW Up to 700 MPa
135	8	3 – 12mm FW ml
141	1	1.4 – 2.6 mm BW sl
141	8-22	1 – 4 mm BW, FW sl
141	23	3 – 8 mm BW, FW ml

Weld performance classes up to CPC1.

Responsible welding coordinator (RWC): Jorge Ruiz de Azúa Fernández. IWE-ES-934. Born 01/08/1969

Deputy Responsible welding coordinator: Alfonso Ruiz de Gordo Lacunza. IWE-ES-265. Born 01/03/1972

Comments: see annex.

Certificate No: LRE/15085/CL1/006/1/18
Valid: from 30 March 2018 to 29 March 2021
Issued on: 30 March 2018
Auditor: Rodrigo González
IWE number: ES-962

Lloyd's Register España, S.A.
 A member of the Lloyd's Register group



José Rivero
 30 March 2018
 Madrid Office



LR031.1.2013.12

José Rivero

Operations Manager of Lloyd's Register España, S.A.

Lloyd's Register España S.A. es una Sociedad Anónima registrada en Madrid, C.I.F. A28591287. Oficina principal: C/Princesa 29, 1º. 28008 Madrid (España). Una compañía subsidiaria del Lloyd's Register Group Limited.

Lloyd's Register Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as the 'Lloyd's Register'. Lloyd's Register assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant Lloyd's Register entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

General regulations (see annex)

Comments:

This Certificate is subject to monitoring of compliance by Lloyd's Register Spain SA as required by the standard EN15085-2: 2007.

Responsible welding coordinator has been assessed and accepted to perform welding procedures and welders qualifications.

Design and purchase of welded parts excluded from certification.

General regulations

According to EN 15085-2

Revocation of the Certificate

The national safety authority or the manufacturer certification body issuing this certificate may revoke the certificate if:

- there are justified doubts as to the proper execution of the welding work according to the stated standards,
- there are justified doubts as to the proper welding coordination according to the stated standards,
- no recognized welding coordinator is available any longer,
- no valid qualification test certificates for the welders and welding operators according to the specified standards are available,
- welders or welding operators without tested qualifications have been entrusted with the execution of welding work under the stated standards,
- other conditions according to the stated standards are no longer satisfied,
- the manufacturer certification body was refused an opportunity to perform the annual verification,
- the welding manufacturer waives the certificate

The welding manufacturer shall acknowledge the revocation in writing to the manufacturer certification body. The manufacturer certification body shall notify the national safety authority.

If a valid certificate is to be renewed, the renewal must be applied for with the manufacturer certification body at least three months before the end of the period of validity of the current certificate.

Distribution list:

1. Applicant (original- Email)
2. LRE Madrid